

Product Safety Recall



YAMAHA YZF-R3/MT03 Motorcycle Radiator Coolant Hose Leak

MODEL	FRAME NUMBER		
	Prefix	To	From
MT03LA 2018	RH072	001001	008240
YZF-R3A 2015 ~ 2016	RH124	001001	001280
YZF-R3A 2018	RH07L	001001	005800
MT03LA 2016 ~ 2018	RH127	001001	001120

WHAT IS THE DEFECT?

Due to insufficient hose material curing at manufacturing, cracking may develop in the radiator coolant hose.

WHAT ARE THE HAZARDS?

This may result in coolant leakage onto the road surface if cracks develop in the aging hose.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the defective Hose/hoses replaced with the countermeasure hose.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

1300 593 600 or visit the website: <https://www.yamaha-motor.com.au/>

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls